

PROPELLER 4N
CH37999B

AIRCRAFT TECHNICAL LOGS

Section 4. PROPELLER

PROPELLER LOG

- 1. Make HARTZELL
- 2. Model HC-C2YR-1BF
- 3. Specification No. P-920
- 4. Date of Manufacture _____
- 5. Hub Serial No. CH37999B
- 6. Blades
 - (a) Design No. F7495S
 - (b) Blade Serial Nos.
 - (i) K01959
 - (ii) K01960
 - (iii) _____
 - (iv) _____
 - (v) _____
 - (c) Pitch Setting
 - (i) Basic _____
 - (ii) High _____
 - (iii) Low _____
 - (iv) Reverse _____

PROPELLER SERVICE AND

DATE	TIME RUN		TOTAL TIME SINCE OVERHAUL		INSTALLATIONS, INSPECTIONS, <small>NOTE: USE BOTH PAGES AND AS MANY LINES AS REQUIRED FOR COMPLETE</small>
	HRS.	MIN.	HRS.	MIN.	
BROUGHT FORWARD	→		0	0	PROPELLER INSTALLED NEW ON DA40 SN 40.634
APRIL 06 2006			4	0	HOURS BROUGHT FORWARD
3-20-07	129	6	129	6	<div style="border: 1px solid black; padding: 5px;"> <p>Date: 3/20/07 Tach: 129.6 Tsmoh: ^{NEW} 129.6 Annual inspection completed this date. Inspected propeller using a checklist prepared in accordance with FAR 43 Appendix D. I certify that this propeller has been inspected in accordance with an annual inspection and was determined to be in an airworthy condition as of this date</p> <p>Angel Colon IA 583176036 </p> </div> <div style="text-align: center; margin-top: 10px;"> <p>Rowan County Airport Date: 4/25/08 Registration: N554DS HOBBS: 336.3 PTT: 336.3</p> <p>Performed Annual Inspection per the Diamond DA40 Maintenances Manual and FAR 43 Appendix D. All ADs checked thru bi-weekly 2008-08. I certify that this aircraft/engine/propeller has been inspected in accordance with an ANNUAL INSPECTION and was determined to be in an airworthy condition. <i>"Pertinent details of the repair are on file under work order No.0644"</i></p> <p style="text-align: right;"></p> <p>Greg Bove A&P 3015153 IA</p> </div>
CARRIED FORWARD					
TOTAL THIS PAGE					
TOTAL FROM PREVIOUS SUMMARY					
TOTAL SINCE MFG.					

MAINTENANCE RECORD

REPAIRS, ADJUSTMENTS, MODIFICATIONS
ENTRIES. DRAW A DIAGONAL LINE THROUGH ANY UNUSED LINES IN DATE AND TIME COLUMNS.

SIGNATURE

LICENCE
NUMBER

AS PER SIC No. SA018500H

~~[Signature]~~
~~[Signature]~~

DA
Q 42
DA
Q 42

MAXIMUM HOURS BETWEEN OVERHAULS _____ HOURS.
OR LIFE

TOTAL THIS PAGE
TOTAL FROM
PREVIOUS PAGES
TOTAL
HOURS